


FOLGER TECHNOLOGIES, LLC

2020 i3 – 3D Printer Kit



BUILD GUIDE

Rev. A

Thank you for your purchase!

We are happy to announce this as our 3rd complete 3D printer kit. The Folger Tech 2020 i3 kit combines the simplicity of an erector set with the power of a much more expensive desktop printer. This kit includes everything you need to assemble the 8 cubic inch print area machine (with the exception of an 8x8" glass surface & the tools required for assembly).

Note From the Author:

This guide was made from the perspective of someone that has never built a 3D printer. I built the printer with only the prototype as a visual reference. Taking pictures each step of the way and making small notations I was able to put together the following guide over the next couple weeks. Once the first draft was completed we had one of our warehouse girls take a kit and try to assemble it. She had zero technical experience and made notes (lots of them) on each page as she went along. She completed her first printer and I took the notes back to my desk to complete this guide. This is the finished product. I look forward to your feedback and hope you enjoy building this extremely fun i3 kit!

Thanks,
Dan
Folger Technologies

Offical RepRap Forum Thread:

<http://forums.reprap.org/read.php?4,512329,512329#msg-512329>

Visit us on IRC:

irc.freenode.net
#folgertech

If you feel you are missing items from your kit or have suggestions for improvements to the build guide please email us at:

orders@folgertech.com

We are also planning on offering 2 upgrades for this kit:

- 1) Extended 200x300MM bed.
- 2) Auto bed leveling with proximity sensor and aluminum plate.

Step 1: Un-box everything and separate like parts into areas you can grab from.

Step 2: Get out your calipers or ruler and separate screws into different piles based on size (believe us, it makes things much easier).


Step 3: Assemble Bottom Half Of Main Frame:

- **Parts Needed:** (2) 365MM 2020, (2) 375MM 2020, (4) SK8's, (1) Motor Mount, (2) 2020 corner brackets.
- **Hardware Needed:** (8) 2020 L Mounts w/ Set Screws, (8) 5mm T-Nuts, (4) 4mm T-Nuts, (4) M4x8MM Pan Head Bolts, (8) M5x8MM Bolts.


1. Take the 375MM 2020 Beam and place it in front of you, we are going to attach the corner brackets, and SK8's before continuing with the frame assembly.

[Insert Picture Here]


2. Using (2) 4MM T-Nuts & (2) 4Mx8MM Pan Head Bolts attach the 2020 corner brackets to the center of the 375MM 2020 Beam spacing them about an inch apart. *Note: this will be adjusted later.*




3. Slide (2) 5MM T-Nuts to the left of the corner brackets, and (2) 5MM T-Nuts to the right of the corner brackets.



4. Attach the (2) SK8's to the M5 T-Nuts using the (4) M5x8MM Bolts. *Note: the tension screws for the SK8's should be facing outwards to make it easier to tighten them later.*



5. Take the other 375MM 2020 Beam and place it in front of you, we are going to attach the motor mount, and the remaining 2 SK8's.
6. Repeat the process from step 3 to attach the remaining 2 SK8's by sliding (4) M5 T-Nuts onto the top of the 2020 beam and attach the remaining (2) SK8's using (4) M5x8MM Bolts.
7. Take the metal motor mount and attach it to the front face of the 375MM 2020 Beam in between the SK8's using (2) M4 T-Nuts & (2) M4x8MM Pan Head Bolts. *Note: this will need to be moved left and right to adjust screws later so you can leave it loose for now.*



8. Now take (4) 2020 L Mounts & the remaining (2) 365MM 2020 Beams. Slide (2) 2020 L Mounts back to back on the top of each of the 365MM 2020 Beams. Each one should look like the picture below. Do not secure these in place as they will be moved later. *Note: Ignore the L Bracket in the left of the picture it shouldn't be there yet.*




9. You can now use the remaining (4) 2020 L Mounts to secure the bottom frame together. Tighten the set screws to lock them in place. Use the below pictures as reference. *Note: The motor mount is not pictured, but should be attached to the rear 2020 beam.*




Step 4: Attach Y Carriage Rails & Bearings:

- **Parts Needed:** (2) 395MM Chrome Rods, (3) LM8UU Bearings, Bottom Frame Assembly.
- **Hardware Needed:** none


1. Place the bottom frame in front of you so the motor mount is at the back of the printer. *Note: This is the front position of the printer. The motor mount is missing from this picture but should be attached to the rear 2020 beam.*




2. Slide (1) 395MM Chrome Rod through the front right SK8 about half way through.



3. Carefully slide (2) LM8UU Bearings onto the Chrome Rod & finish pushing the Chrome Rod through to the other SK8. *Be careful not to hit the corner of the rod on the inside of the LM8UU which can cause bearings to fall out.*



4. Similar to step 3 slide the remaining (1) 395MM Chrome rod into the left side SK8 and slide (1) LM8UU Bearing onto the rod.



5. Be Sure to tighten the tension screws on the (4) SK8's to secure the chrome rod's in place.

Step 5: Attach & Assemble The Upper Frame

- **Parts Needed:** (2) 295MM 2020 Beam, (1) 375MM 2020 Beam, Bottom Frame Assembly.
- **Hardware Needed:** (3) 2020 L Mounts w/ Set Screws.


1. Take the (2) 295MM 2020 Beams and attach them vertically to the left and right side of the Bottom Frame Assembly using the (2) 2020 L Mount's on each side that we placed in step 3:8. Before securing them make sure the back side of the beam is 90MM from the back of the printer.



2. Before attaching the top we are going to attach (1) 2020 L Mount to the outside of the left most vertical 295MM 2020 Beam for the Spool Holder which we will attach later.



3. Now attach the remaining (1) 375MM 2020 Beam to the top of the (2) vertical 295MM 2020 Beams using (2) 2020 L Mounts w/ Set Screws to secure them in place.




Step 6: Assemble The Aluminum Heat Bed Plate

- **Parts Needed:** (1) Aluminum Bed Plate, (3) Printed Bearing Mounts, (1) Printed Belt Carriage.
- **Hardware Needed:** (6) Small Zip Ties, (6) M3x20MM Bolts, (2) M3x12MM Bolts (8) M3 Nylock Nuts.

1. Remove the blue protective layer off both sides of the Aluminum Bed Mount.




2. Take the (3) Printed Bearing Mounts and attach (2) Small Zip Ties to each by sliding the Zip Tie through the guide holes (as pictured).




3. Using the (6) M3x20MM Bolts & (6) M3 Nylock Nuts, attach the Printed Bearing Holders to the Aluminum Bed Plate. Use the (2) M3x12MM Bolts and (2) M3 Nylock Nuts to attach the Printed Belt Carriage to the Aluminum Bed Mount using the pre drilled holes. *Note: the opening on the Printed Belt Carriage is facing the side with 2 bearing holders.*



4. Now we are going to attach the Aluminum Bed Mount to the bearings on the Bottom Frame Assembly of the printer by pushing them down into the LM8UU Bearings. Line up the Printed Bearing Holders over the LM8UU's attached to the Chromed Rod and apply enough pressure to snap the bearings into the Printed Bearing Mounts. *Note: you should feel a small pop as it sets into the grooves.*



5. Tip the frame backward and close the Small Zip Ties that you previously attached to the Printed Bearing Holders over the LM8UU Bearings securing them in place. *Note: Once tightened you can clip the excess material from the Small Zip Ties.*




Step 7: Solder The MK2B Heated Bed & Attach Thermistor

- **Parts Needed:** (1) MK2B Heated Bed, (1) Thermistor, (1) xM Black 16 Gauge Wire, (1) xM Red 16 Gauge Wire.
- **Special Tools Needed:** Soldering Iron, Solder, Kapton Tape

1. Prepare your MK2B Heated Bed to be soldered.



2. Apply solder to contacts #1, #2, & #3.




3. Strip the ends off and apply solder to one end of both the Black & Red 16 Gauge Wire.



4. Solder the stripped and soldered end of the Black 16 Gauge Wire to both contacts #3 & #2. *Note: This is critical, if you do not make contact with both #3 & #2 you will only be running at 12v and will not be able to reach max bed temp.*



5. Solder the stripped and soldered end of the Red 16 Gauge Wire to contact #1.



6. Place the glass of (1) Thermistor into the small hole in the center of the heated bed.




7. Using the provided Kapton Tape, secure both the Thermistor and the Red & Black 16 Gauge wire to the bottom of the heated bed. *Note: use these pictures as a guideline but you can use more/less tape and position the wires as you see fit.*



Step 8: Attach the Heated Bed to the Aluminum Bed Plate.

- **Parts Needed:** (1) MK2B Heated Bed Pre Wired from Step 7
- **Hardware Needed:** (4) Springs, (4) Thumb Screws, (4) M3x16MM Bolts

1. Feed (1) M3X8MM Bolt through each corner hole on the MK2B Heated Bed > Spring > Aluminum Bed Plate > Secure with (1) Thumb Screw. *Note: wires should be coming out the back of the printer. Thumb screws just need to be hand tight for now and can be adjusted later.*





Step 9: Attach Motors & Motor Mounts

- **Parts Needed:** (2) Metal Motor Mounts, (2) Acrylic Rod Keepers, (1) 4.8 Motor, (2) 2.6 Motors
- **Hardware Needed:** (6) M4 T-Nuts, (6) M4x8MM Pan Head Bolts, (4) M3x8MM Bolts, (8) M3x12MM Bolt, (12) Lock Washers



1. Gather the required parts & hardware.





2. Take the (2) Metal Motor Mounts and (2) Acrylic Rod Keepers and attach them to the (2) 2.6 Motors using (8) M3x12MM Bolt & (8) Lock Washers. *Note: one acrylic rod keeper should have the small hole facing right, and one should have hole facing left, as pictured. Wire harness should be facing the corner of the bracket.*



3. Mount the (1) 4.8 Motor to the Metal Motor Mount that we attached to the Bottom Frame Assembly earlier in the build guide using (4) M3x8MM Bolts & (4) M3 Lock Washers.




4. Attach the (2) Metal Motor Mounts with the attached motors and acrylic rod keepers to the top right & left corners on the front of the 2020 Frame using (3) M4x8MM Pan Head Bolts and (3) M4-T-Nuts per side. *Note: the small holes in the acrylic rod keepers should be facing the outside of the printer. These don't need to be secured to tightly as we will be raising them later.*




Step 10: Assemble Z Carriage

- **Parts Needed:** (7) LM8UU Bearings, (1) 2.6 Motor, (1) 3D Printed: Extruder Carriage, (1) 3D Printed: Left Side, (1) 3D Printed: Right Side, (1) Folger Tech Direct Drive Extruder: Pre Assembled, (2) F623Z Bearings, (1) 20T Pulley, (1) 1M GT2 Belt, (2) 365MM Chromed Rod
- **Hardware Needed:** (3) M3x20MM Bolts, (1) M3x16MM Bolt, (4) M3 Nylock Nuts, (2) M5 Nuts, (8) Zip Ties

1. Insert (2) LM8UU Bearings into the (1) 3D Printed: Right Side by pressing them firmly. *Note: You can use the table to push them into place if more force is required.*



2. Insert (1) M5 Nut into the pre cut slot provided.



3. Attach the (1) 2.6 Motor to the (1) 3D Printed: Right Side using (3) M3x20MM Bolts. *Note you want the motor wire connectors to be facing up so using the picture as a reference it would be facing the upper left.*



4. Attach the (1) 20T Pulley onto the shaft of the (1) 2.6 Motor and secure with the set screws. Set this aside for now. *Note: Tooth side down on the pulley.*




5. Take the (1) 3D Printed: Left Side and Place the 2 Bearings into the spot provided, just like you did with the Right Side.




6. Place the remaining (1) M5 Nut into the spot provided on the (1) 3D Printed: Left Side.




7. Take the (2) F623ZZ Bearings and using (1) M3X16MM Bolt and (1) M3 Nylock Nut to secure the bearings into the (1) 3D Printed: Left Side as pictured. Set aside for now.




8. Take the (1) 3D Printed: Extruder Carriage and place (6) Zip Ties into the slots provided to later secure the bearings.




9. Press (3) LM8UU Bearings into the (1) 3D Printed: Extruder Carriage. Secure into place using the Zip Ties & Clip the ends off the Zip Ties. *Note: Use the table to press the bearings into place if you are having trouble getting them to lock in.*




10. Very carefully slide the (2) 365MM Chromed rod through the bearings in the (1) 3D Printed: Extruder Carriage. *Note: Be very careful when pushing the rod through the bearings not to push out the ball bearings,*




11. Take the 3D Printed Part: Extruder Carriage (with the rods and bearings attached, the 3D Printed Part: Left Side (assembled) and the 3D Printed Part: Right Side (assembled) and set them in front of you. You should have the parts laid out in front of you as pictured. *Note: these are mirrored to how they will be when attached to the printer so don't get confused with how we define left and right in the next step.*



12. Push the 2 ends of the Chrome Rods on the left into the 2 holes in the 3D Printed: Right Side. Push them in so they are snug, we will have to adjust this later.



13. Push the 2 ends of the Chrome Rods on the right into the 2 holes in the 3D Printed: Left Side.




14. Push the outside 3D Printed Left/Right together to snug up the assembly. **The inner diameter (inside the Right Plastic to the Inside Left Plastic) should be 300MM.** This is important to ensure it fits on the printer later.



15. We are now going to take 1M of GT2 and attach it to the back of the 3D Printed: Extruder Carriage by looping it around the right side upper belt block as pictured below. *Note: allow a little extra slack we will secure this later with zip ties.*



16. Now take the rest of the belt, feed it over the top of the FZ623ZZ Pulleys on the right side and back to feed under and above the 20T Pulley on the motor on the left side. Bring the belt back and attach to to the left side belt block the same way you did above (but on the opposite side). **Trim the extra belt.** *Note: you want the belt to be tight but not to tight, we can always add a belt spring later to adjust tension.*




17. Now take (2) Zip Ties and secure the overhanging GT2 belt to the upper belt on each side as picture below.




Step 11: Attach the Extruder to the X Carriage

- **Parts Needed:** (1) Extruder Assembly, (1)X Carriage (assembled in step 10)
- **Hardware Needed:** None.

1. Remove the 2 screws from the top of the motor is part of the Extruder Assembly.




2. Using the 2 screws removed in step 1, attach the motor to the X Carriage by screwing it to the 3D Printed Part: Extruder Carriage as pictured.




Step 12: Attach Chrome & Threaded rod to the assembled X Carriage.

- **Parts Needed:** (2) 235MM 5MM Threaded Rod, (2) 320MM 8MM Chrome Rod, (1) Assembled X Carriage
- **Hardware Needed:** None

1. Take the Assembled X Carriage and the (2) xxMM 5MM Threaded Rod & the (2) xxMM 8MM Chromed rod and lay them out in front of you like so:




2. Thread the 235MM 5MM Threaded Rod through the 5mm nut that was previously inserted into the Left and Right 3D Printed Parts. Thread it about half way through so the same amount of thread is showing on the top and bottom of the part. Feed the 320MM 8MM Chrome Rod through the bearings on the Left and Right 3D Printed Parts as pictured below. *Note: Be careful when putting the chrome rod in not to push out the ball bearings.* **Set this aside for later**




Step 13: Assemble The Front Pulley Assembly

- **Parts Needed:** (2) F623ZZ Bearings, (1) 623ZZ Bearing
- **Hardware Needed:** (1) M3x30MM Bolt, (4) M4 Large Washers, (2) M3 Washers, (1) M3 Nylock Nut, (2) M4x8MM Pan Head Bolts.

1. Assemble the hardware in the following order going through the 2020 corner brackets you previously attached to the front of the frame during step 3 of assembly.




M3x30MM Bolt > M4 Large Washer > **2020 Corner Bracket** > M4 Large Washer > **M3 Washer** > F623ZZ Bearing (flange out) > **623ZZ Bearing** > F623ZZ Bearing (flange out) > **M3 Washer** > M4 Large Washer > **2020 Corner Bracket** > M4 Large Washer > **Nylock Nut**.




Step 14: Attach the Pulley and Belt to the Y carriage.

- **Parts Needed:** (1) 20T Pulley, (1) ~1M Meters GT2 Belt
- **Hardware Needed:** (2) Zip Ties




1. Attach the (1) 20T Pulley to the Large Motor attached to the bottom frame using the set screws in the pulley to secure it in place. *Note: Teeth on motor side.*



2. Tip the printer back and using the same method used for the X Carriage belt installation we are going to attach the (1) xM GT2 Belt to the Y carriage.




3. Attach the belt to the back end of the 3D Printed: Belt Carriage on the bottom of the Aluminum Mount plate, leaving enough slack to zip tie it later. Feed the belt around the 20T Pulley on the motor and then bring it to the front of the printer and go under and above the F23ZZ bearing mount you assembled in Step 12. You can then feed it back and attach it to the front part of the 3D Printed: Belt Carriage again leaving enough slack for zip ties.




Step 15: Attach the Couplings and SHF8UU in preparation for the X Carriage to be attached in the next step.

- **Parts Needed:** (2) 5x5 Couplings, (2) SHF8UU
- **Hardware Needed:** (4) M4x14MM Black Bolts, (2) M4 T-Nuts


1. Before we can attach the SHF8UU we need to remove 2 set screws from (2) 2020 L Brackets that are attached to the frame. With the printer in front of you, remove the 2 set screws from the 2020 L Brackets that are securing the top frame to the bottom frame on the front of the printer. *Note: These are the set screws directly Below the small motors on the **bottom frame**.*



2. Now take (1) M4X14MM Bolt and put it through the right hole in the SHF8U (as Pictured) and attach (1) M4 T-Nut to the other end of the bolt loosely, we are going to place this on the bottom frame and use the hole from the removed set screw to attach the other M4X14MM Bolt securing both the frame and the SCH8UU in place. Tighten Both Screws. *Note: the tension bolt on the SCH8UU is facing forward to allow access to tighten it later.*



3. Repeat this process for the opposite side.
4. Attach the (2) 5x5 Couplings to each of the 2.6 Motors mounted to the top of the frame using the 2 set screws provided in the coupling, leave enough over hang so that the second set of set screws in the coupling can be later used to secure the threaded rod we will be inserting.




Step 16: Attach X & Z Assembly to the Printer.

- **Parts Needed:** X & Z Assembly, Assembled Frame
- **Hardware Needed:** None

1. First loosen both of the motor mounts on the top of the printer that are for the Z Axis and pull them up as far as they will go. Secure them in place by tightening one of the M4 bolts. This is just to give you clearance when attaching the X & Z Assembly.





2. Take your X & Z Assembly you previously assembled and set the chrome rods into the SCH8UU's on the bottom of the frame directly below the Z Axis Motors that we just raised. *Note: make sure they are pushed in all the way so they touch the 2020 beam below them.*



3. Now we are going to lower each of the motor brackets that we raised in step 1 so that they drop down allowing the top of the chrome rod for the X & Z Assembly to sit in the hole in the Acrylic Rod Keeper. *Note: Try to keep the bracket squared but make sure the chrome rod is fully seated in the hole.*



4. Now screw the 5MM Threaded rod until it feeds up into the 5x5MM Coupling attached to the motor. You want the threaded rod to be snug against the tip of the motor shaft inside the coupler. If you go too far it will try to push the 5MM Nut out of the 3D Printed part below so pay close attention. Once you are confident the rod is touching the motor shaft you can tighten the 2 set screws on the 5x5MM Coupling to secure it in place. Repeat this for both sides.





Step 17: Attach the Power Supply.

- **Parts Needed:** (1) Power Supply, (2) 2020 Corner Brackets
 - **Hardware Needed:** (4) M4X8MM Pan Head Bolts, (x2) M4 T-Nuts
1. Using (2) M4X8MM Pan Head Bolts attach (2) 2020 Corner Brackets to the left side of the power supply. *Note: direction based on the wire connectors facing the top front of the power supply.*



2. Using (2) M4X8MM Pan Head Bolts and (2) M4 T-Nuts attach the power supply to the inner side of the right vertical 2020 Beam. *Note: the power supply can rest on the bottom frame.*



Step 18: Attach the Acrylic Electronics Mount


- **Parts Needed:** (1) Acrylic Hardware Mount
- **Hardware Needed:** (2) M4x10MM Pan Head Bolts, (1) M4 T-Nut

1. Similar to attaching the SCH8UU in previous steps, we will be removing a set screw from the 2020 L Bracket that is directly above the power supply 2020 Bracket on the vertical 2020 beam.
2. Attach the (1) Acrylic Hardware Mount to the 2020 frame directly above the power supply by using the (2) M4X8MM Pan Head Bolts and using the 2020 L Bracket already in place for the top screw and (1) M4 T-Nut for the lower screw hole. *Note: The holes on the acrylic are differently spaced; if they don't line up try the other side.*




Step 19: Assemble & Mount the Electronics


- **Parts Needed:** (1) Mega Board, (1) Ramps Board w/ jumpers & power connector, (4) A4988 Stepper Drivers w/ heatsinks
- **Hardware Needed:** (3) M3X30MM Bolts, (x3) Nylock Nuts



1. Attach the jumpers (included in ramps bag) to the (1) Ramps Board. Each stepper driver requires 3 jumpers. *Note: we are also placing jumpers on the 5th slot in case you decide to upgrade to a dual extruder sometime in the future.*




2. Attach the (1) Ramps Board to the (1) Mega Board. This can only be installed one way, line up the pins on the underside of the Ramps Board to the connectors on the Mega Board and firmly press them into place.




3. Attach the heat sinks that came with the (4) A4988 Stepper Drivers to the Stepper Drivers by removing the sticky back protector from the bottom of the heat sink and sticking it to the chip on the top of the Stepper Drivers



4. Attach the (4) A4988 Stepper Drivers to the Ramps Board. Make note of the orientation of the steppers when attaching them. The tuning screws on all of them should be facing to the left of the power connections on the Ramps Board. *Note: line up the pins with the connectors starting from the right as there are only just enough holes for the pins as necessary so if you are off by 1 you will come short at the end.*




5. Attach the now finished Electronics Assembly to the Acrylic Electronics Mount that we previously mounted to the printer using the (3) M3X30MM Bolts and (3) Nylock Nuts. *Note: The power connections and usb port should be facing the outside of the printer.*




Step 20: Attach the Motor Wires

- **Parts Needed:** (5) Motor Cables with Pre Wired Ends
- **Hardware Needed:** None


1. Take the white end from all of your Motor Cables and plug one of them into each of the motors so that each motor has a wire attached to it.




2. Now take (2) wires from the Z axis (top) motors and plug them into the ramps board under the left most top stepper driver. *Note: these motors mirror each other so it doesn't matter which is on top and which is on the bottom.*




3. Take the wire from the Y Carriage Motor and plug it in under the 2nd (middle) stepper driver.



4. Take the wire from the Z Carriage Assembly (the motor with the 20T Pulley) and plug it in under the 3rd (right most) stepper driver.




5. Take the wire from the Extruder Assembly and plug it under the bottom right most stepper driver.





Step 21: Wire the Heated bed and the Extruder Heater to the Ramps Board

- **Parts Needed:** Heated Bed Wires, Extruder Heater Wires
- **Special Tools Needed:** Wire Strippers


1. Take your Black & Red 16 Gauge wires from your heated bed and strip the ends off exposing the wiring underneath as pictured.




2. Use a flat screwdriver to open up the +/- ports of D8 on the Ramp Board's blue power strip. Plug the Black (-) 16 Gauge wire into the first hole (-) and plug the Red (+) 16 Gauge wire into the second hole (+). Tighten down the flat screws to secure the wire in place.



3. Take the red wires from the extruder and strip the ends off to expose a small amount of wire, as pictured.




4. Use a flat screwdriver to open up the +/- ports of D10 on the Ramp Board's blue power strip. Plug the 2 wires into the +/- ports of D10 and secure the wire in place by tightening down the flat screws. *Note: these have no polarity so it doesn't matter which wire goes into which port.*





Step 22: Attach Heated Bed and Extruder Thermistors

- **Parts Needed:** Heated Bed Thermistor Wires, Extruder Thermistor Wires, (4) Small Crimps, (2) 2 Pin Molex Connectors
- **Special Tools Needed:** Crimp Tool or Pliers, Wire Strippers


1. First take both pairs of thermistor wires (Heated Bed & Extruder) and strip the ends off as pictured below. Attach the crimp ends to each wire using either pliers or a crimp tool if you have one available. Plug the now crimped ends into the black 2 Pin Molex Connector (polarity does not matter here) as pictured below.



2. Take the Extruder Thermistor and attach it to the ramps board. This thermistor plugs into the pins directly below the left most top Stepper Driver on the far right side of the pin set.




3. Take the Heated Bed Thermistor and attach it to the ramps board directly to the left and right next too the Extruder Thermistor wire.




Step 23: Mount & Wire the End Stops

- **Parts Needed:** (3) End Stops w/ Wires, (3) 3D Printed End Stop Mounts
- **Hardware Needed:** (3) M3X8MM Bolts, (3) M3X18MM bolts, (6) M3 Nylock Nuts


1. Plug the white end of the wires into each of the End Stops.




2. We are going to attach the Z Axis End Stop. Take (1) End Stop and mount it to (1) 3D Printed End stop using (1) M3X8MM Bolt & (1) M3 Nylock Nut as pictured. *Note: This only requires 1 bolt, to the right of the limit switch.*




3. Mount the now assembled End Stop to the vertical chrome rod on the right side of the printer using (1) M3X18MM Bolts and (1) M3 Nylock Nut.




4. Position the End Stop so that the limit switch makes contact with the 3D Printed: Right Side plastic part. *Note: when homing the printer you want the Z axis to come down and click the limit switch at a point where the Hot End Nozzle is only a paper width from the heated bed. You can eyeball it for now, and move it up and down when you calibrate it later so that it is in the correct vertical position.*




5. Attach another End Stop to one of the 3D Printed End Stop Mounts using (2) M3X8MM Bolts and (2) M3 Nylock Nuts.




6. Attach the now assembled End Stop just to the left of the 3D Printed: Right Side on the lower Chromed Rod using (1) M3X18MM Bolts. *Note: the limit switch should be hitting the motor on the extruder when it moves over. Position the End Stop on the Chromed Rod so that when the motor makes contact with the switch the Extruder Nozzle is just to the right edge of the heated bed print area.*




7. We are going to mount the Y carriage End Stop. This one is a bit trickier to mount. The End Stop mounts to the 3D Printed End Stop Mount using the same (1) M3X18MM Bolt and (1) M3 Nylock Nut that is used to mount the 3D Printed End Stop Mount to the Chromed Rod. Clip the 3D Printed End Stop Mount to the rear of the printer on the right most Chromed Rod about an inch from the SK8. *Note: this limit switch should hit the 3D Printed Bearing holder under the Aluminum Mount Plate and you want the switch to make contact when the Extruder Nozzle is at the front most of the heated bed print area.*




8. Take the end of the wire from the Z Axis End Stop. The End Stops plug into the pin set that is on the lower left corner of the ramps board. There are 6 rows of pins. Plug the End Stop into the 3rd row over. Use the picture as a reference. The red wire should be facing up, **if plugged in backwards it will short the ramps causing permanent damage.**



9. Take the end of the wire from the Y Carriage End Stop. Skip a row and plug this End Stop into the 5th row, one over from the previous End Stop. Use the picture as a reference. The red wire should be facing up, **if plugged in backwards it will short the ramps causing permanent damage.**



10. Take the end of the wire from the X Carriage End Stop. Again you are going to skip a row from the previous plugged in end Stop and plug this End Stop into the 7th row. Use the picture as a reference. The red wire should be facing up, **if plugged in backwards it will short the ramps causing permanent damage.**




Step 24: Wire Power Cable to the Power Supply

- **Parts Needed:** (1) Black Power Cable
- **Special Tools Needed:** Multimeter

1. Take the Black Power cable and cut off the female end of the cable. Strip off a bit of the black outer protector, and strip the wires inside as pictured.




2. Because the wire colors can differ from kit to kit, use a multimeter to determine which wires are live and which wire is the ground. We are going to attach the stripped ends of the power supply to contacts #7, #8, and #9 on the power supply. Unscrew the screw for each contact and place the stripped end of the wire under the screw before tightening it back down. If you have the same cable pictured, the 2 black wires can be wired into #8 and #9 which are the Line and Neutral contacts (*polarity doesn't matter with these 2*). The blue wire can be wired into #7 which is the Earth Ground.




Step 25: Wire the Ramps to the Power Supply.

- **Parts Needed:** (2) 240MM 16 Gauge Red Wire, (2) 240MM 16 Gauge Black Wire, (1) Green Ramps Connector
- **Hardware Needed:** None


1. Take all both the (2) 240MM 16 Gauge Red Wire and the (2) 240MM 16 Gauge Black Wire and strip the ends off both sides slightly, as pictured.




2. Insert one end of each of the 16 gauge wires into the (1) Green Ramps Connector using a small flat head screwdriver to open up the port and feeding the wire ends into it. You can then tighten down the screw to secure the wire in place. It should be Red, Black, Red, Black as pictured below. You can then take it and plug it into the ramps board.



3. We are now going to wire the opposite ends of these wires to the Power Supply. Take the ends of the (2) 16 Gauge Red Wire and attach them to contacts #2 and #3 on the power supply. These are the positive wires.




4. Take the ends of the (2) 16 Gauge Black Wire and attach them to contacts #4 and #5 on the power supply. These are the negative wires.




Step 26: Attach Wire Extension to Extruder Fan & Wire it to The Power Supply.

- **Parts Needed:** (1) 1M 22 Gauge Black Wire, (1) 1M 22 Gauge Red Wire
- **Special Tools Needed:** Soldering Iron, Kapton Tape

1. Cut the end off of the Extruder Fan and Strip the ends of the wires slightly.




2. Take 1M of 22 Gauge Black & Red wire and strip a small amount off of each end of the wires. Using a soldering iron attach the wires to the Extruder Fan wires.




3. Use either Kapton tape (included) or another non conductive material to cover the exposed wires and stop them from pulling apart easily.



4. Plug the other end of the now extended fan wires to the Power Supply. You can plug the Red Wire to contact #1, and the Black Wire to contact #6. This will allow your fan to run all the time and limit jamming or clogging in your extruder. *Note: this is our preferred method for wiring the fan.*




Step 27: Verify your wiring using the below pictures as a reference.



Step 28: Mount Filament Feed Assist

- **Parts Needed:** (1) Wire Keeper
- **Hardware Needed:** (1) M3x30MM Bolt, (1) M4 Washer


1. Remove the bolt from the front left corner of the upper left Z Axis Motor and replace it with (1) Wire Keeper holding it in place by using (1) M3X30MM Bolt and (1) M4 Washer in the empty socket from the removed screw.



Step 29: Attach the Spool Holder

- **Parts Needed:** (1) 140MM 2020 Beam
- **Hardware Needed:** (1) 2020 L Bracket w/ Set Screw


1. Using the (1) 2020 L Bracket we left in place on the left side of the printers vertical 2020 beam, attach the (1) 140MM 2020 Beam to it. Then place your last (1) 2020 L Bracket on the top of the 140MM 2020 Beam to stop your spool of filament from sliding off.



Step 30: Wire Cleanup & Cosmetics

- **Parts Needed:** (1) Wire Keepers, (1) 1M Wire Wrap, (1) 2M Black 2020 Wire Conceal
- **Hardware Needed:** (2) M4 T-Nuts, (2) M4 Pan Head Bolts

1. This step is honestly purely user preference. If you prefer to copy our printer we use the wire wrap for both the extruder wires and the X axis motor wires. We use the (1) Wire Keeper on the top most 2020 on the printer to attach the extruder cables for a nice clean look and to keep them from floating around. You can use these pictures as reference. Use zip ties to clean up the wiring and tuck it in next to the Ramps Board. *Note: Ignore the black cable with the extruder wires these pictures were taken after we installed a proximity sensor to test out our upgrade kit.*



2. You can use the 2M of Black 2020 Wire Conceal you were provided to hide wires inside the 2020 beam slots, or just for purely cosmetic purposes on the face of the printer. Some people even prefer to cut all their wires short and put new crimps on the end, we didn't on this build to make it a bit easier.

Congratulations, you have officially finished building the Folger Tech 2020 i3 3D Printer Kit!! You are now ready to follow up with the configuration guide and get started with your first print! If you have any suggestions for changes to this guide, spots you thought need improvement or steps that might have been missing all together please email orders@folgertech.com. We value your feedback and we want to make sure this guide is as easy to follow as possible!

Thank you for your continued business and support!

- The Folger Tech Team